



*Inclinometer  
angle  $\alpha$*



T1  
T2



**Kyphosis**

= angle  $\alpha$  + angle  $\beta$

*Inclinometer  
angle  $\beta$*



T12  
L1