

Table 2: Latrine availability and its condition, among the rural community of Bahir Dar Zuria District, May 2012 (n= 608)

<b>Variables</b>	<b>Frequency</b>	<b>Percent</b>
<b>Having latrine(n=608)</b>		
Yes	355	58.4
No	253	41.6
<b>Type of latrine(n=355)</b>		
Pit latrine	355	100.0
Others	0	0
<b>Availability of latrine Construction material(n=608)</b>		
Available	551	90.6
Un available	57	9.4
<b>Functional of latrine(n=355)</b>		
Yes	135	38.0
No	220	62.0
<b>Latrine squat cover(n=355)</b>		
Yes	7	2.0
No	348	98.0
<b>Latrine construction year(n=355)</b>		
< 2 year	168	47.3
=> 2 year	187	52.7
<b>Latrine condition(n=355)</b>		
Need maintenance	202	56.9
No need maintenance	153	43.1
<b>Maintenance part of latrine(n=202)</b>		
Super structure	53	26.2
Slab	20	9.9
Roof	113	55.9
Dug	16	7.9
<b>Availability of Hand washing facility presence(n=355)</b>		
Yes	22	6.2
No	333	93.8
<b>Detergent at the Hand washing facilities(n=22)</b>		
Nothing	18	81.8
Soap	3	13.6
Ash	1	4.6
<b>Distance of Latrine from home (n=355)</b>		
<6 meters	114	32.1
6-10 meters	102	28.7
>10 meters	139	39.2